

INDEX

DREDGING	3
Rio Salado	Rio Salado
ROUTES	4
Rural Road improvement. Lot 1. Rural Road improvement. Lot 2	Rural Road improvement. Lot 2
ROCK DRILLING	5
Rock Drilling in Claro River	Rock Drilling in Quinto River

DREDGING

Rio Salado

Where Buenos Aires, Argentina.

Work Adequacy of the Salado river Section. 3rd track Sector III

Description Consisted on the excavations of margins and dredging the

riverbed of the Salado River, between survey of 223,918 km to 285,518 km, excavation with backhoes and dredges, and

transport to venues for the final disposal of soils.

Amount 58.110.250



Rio Salado

Where Buenos Aires, Argentina.

Work Adequacy of the Salado river Section. 3rd track Sector III

Description Consisted on the excavations of margins and dredging the

riverbed of the SaladoRiver, between survey of 223,918 km to 285,518 km, excavation with backhoes and dredges, and

transport to venues for the final disposal of soils.

Amount 40.000.000



Coaster Ave. Ciudad de Concepción

Where Entre Ríos, Uruguay.

Work Construction of Coaster Ave.

Description Dredging the Uruguay River, a navigable section of the river;

and refulado of dredged material for an embankment construction of the on the trace to settle the coastal avenue,

refulado a distance of approximately 1,500 meters.

Amount 32.452.315



ROUTES

Rural Road improvement

Where Córdoba, Argentina.

Work Improvement of rural roads. Lot 1.

Description It consisted in improving rural roads and aimed to add value

to the tertiary road network, on a important production area; for which the following works were executed: land clearing, forest clearing, grubbing, preparing the ground; and construction of compacted fill; granular subbase; and

granular base.

Amount 7.214.507



Rural Road improvement

Where Córdoba, Argentina.

Work Improvement of rural roads. Lot 2.

Description It consisted in improving rural roads and aimed to add value

to the tertiary road network, on a important production area; for which the following works were executed: land clearing, forest clearing, grubbing, preparing the ground; and construction of compacted fill; granular subbase; and

granular base.

Amount 2.479.706



Rural Road improvement

Where Córdoba, Argentina.

Work Improvement of rural roads. Lot 2.

Description It consisted in improving rural roads on dairy areas and aimed

to add value to the tertiary road network, on a important production area; for which the following works were executed: land clearing, forest clearing, grubbing, preparing the ground; and construction of compacted fill; granular

subbase; and granular base.

Amount 2.380.400



ROCK DRILLING

Rock Drilling in Claro River

Where San Luis, Argentina.

Work Rock Drilling in Claro River.

Description Rock drilling performance for the foundations treatment;

perforations were made rotopercussion, in various diameters, with different inclinations and different depths, in order to perform consolidation injections; waterproofing;

and anchors.

Amount 5.546.000



Rock Drilling in Quinto River

Where San Luis, Argentina.

Work Rock Drilling in Quinto River.

Description Rock drilling performance for the foundations treatment;

perforations were made rotopercussion, in various diameters, with different inclinations and different depths, in order to perform consolidation injections; waterproofing; and anchors.

Amount 3.174.000

